

## BHSENS TPMS SERVICE KITS

Bei einem guten Fahrzeugservice sollten die Reifventile bei jedem Reifenwechsel fachgerecht getauscht werden. Genauso auch die Serviceteile des RDKS-Sensors (z.B. Ventileinsatz und Ventilkappe sowie Überwurfmutter und Gummidichtung).

Entdecken Sie jetzt das umfassende Angebot von BHSens an RDKS-Service-Kits, die auch für andere Hersteller (RDKS-Sensormarken) geeignet sind.



| Art.-Nr.        | Artikelbezeichnung                | passend für                                      | Anzugsdrehmoment Überwurfmutter | Anzugsdrehmoment Schraube |
|-----------------|-----------------------------------|--|---------------------------------|---------------------------|
| <b>381 0303</b> | Universal TPMS Service Kit USVK01 | BHSens, Continental, Pacific, Schrader, TRW      | 4,0 Nm                          | ...                       |
| <b>381 0304</b> | TPMS Service Kit SVK001           | Pacific Snap-in Sensor mit Clip-Befestigung      | ...                             | ...                       |
| <b>381 0305</b> | TPMS Service Kit SVK002           | Schrader Faraday und EZ Sensor 2.0               | 8,0 Nm                          | ...                       |
| <b>381 0307</b> | TPMS Service Kit SVK003           | Schrader Faraday und EZ Sensor 2.0               | 1,4 Nm                          | 1,4 Nm                    |
| <b>381 0308</b> | TPMS Service Kit SVK004           | Schrader Faraday und EZ Sensor 2.0               | 8,0 Nm                          | 1,4 Nm                    |
| <b>381 0309</b> | TPMS Service Kit SVK005           | Schrader Gen Gamma/Delta, EZ Sensor 2.0          | 6,0 Nm                          | ...                       |
| <b>381 0310</b> | TPMS Service Kit SVK006           | Schrader SI/Faraday                              | ...                             | 1,4 Nm                    |
| <b>381 0311</b> | TPMS Service Kit SVK007           | Conti TG1C                                       | ...                             | ...                       |
| <b>381 0314</b> | TPMS Service Kit SVK008           | Conti TG1C                                       | 8,0 Nm                          | ...                       |
| <b>381 0315</b> | TPMS Service Kit SVK009           | Hyundai, Kia                                     | 8,0 Nm                          | ...                       |
| <b>381 0316</b> | TPMS Service Kit SVK010           | Pacific Snap-in Sensoren mit Schraub-Befestigung | ...                             | 1,4 Nm                    |
| <b>381 0319</b> | TPMS Service Kit SVK012           | Schrader Gen Gamma/Delta, EZ Sensor 2.0          | 6,0 Nm                          | ...                       |
| <b>381 0320</b> | TPMS Service Kit SVK014           | Schrader Gen 2/3                                 | 8,0 Nm                          | ...                       |
| <b>381 0321</b> | TPMS Service Kit SVK015           | Conti TG1C                                       | 8,0 Nm                          | ...                       |
| <b>381 0324</b> | TPMS Service Kit SVK018           | Pacific Gen 1/2/3/4                              | 4,0 Nm                          | ...                       |
| <b>381 0325</b> | TPMS Service Kit SVK019           | BHSens RDV021                                    | 4,0 Nm                          | ...                       |
| <b>381 0326</b> | TPMS Service Kit SVK020           | Conti TG1D mit Clip Befestigung                  | ...                             | ...                       |
| <b>381 0327</b> | TPMS Service Kit SVK032           | BH Sens OEM Sensor                               | ...                             | 1,4 Nm                    |